


Budova L
Půdorys 1PP



KL 0273

TOSHIBA
CAS-48CA-ES

KL 0271

DAIKIN


2x35k2v1B

KL 0270

DAIKIN

QX 35 K2V13

Budova L
Pūdorys 1NP



KL 0274
TOSHIBA
RAV-180A-P

TOSHIBA

RAE-18N3AV2-E

KL 0119

SANTO
KL 0272
Budova L
Pudorys 2NP

KL 0118

KL 0127

TOSHIBA

RAE-18N3AV2-E

TOSHIBA

SLW

KL 0276

TOSHIBA

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E

RAE-18SA-E