



3N~50Hz 380V/415V



NOTES:
 1. WIRING TO BE IN ACCORDANCE WITH THE LOCAL ELECTRICAL REGULATIONS.
 2. EARTH WIRING.
 3. TO INSTALL HEAD PRESSURE CONTROL. SEE REGULATION ABOVE. REMOVE WIRE FROM TERMINAL 12 AND 13. REMOVE JUMPERS BETWEEN TERMINALS 9, 10, 11, 12 AND 13.
 4. IF THE COMPRESSOR ROTATES REVERSLY, IT MAY BE DAMAGED.



FIELD SUPPLY JARIS	
SSS	MAIN DISCONNECT
K3T	STOP
K3L	START (UP 115V) (OPTIONAL, 24V FAN)
P1	24V SPEED CONTROLLER PRESSURE TRANSDUCER
P2	FAN SPEED CONTROLLER SPEED TRANSDUCER
K1M	COMPRESSION MOTOR
K2T	LOCK OUT THERMAL RELAY (24V FAN)
K3T	COMPRESSION CONTACTOR
K4A	COMPRESSION OVERCURRENT RELAY (24V FAN)
P2	CRANKCASE HEATER
CR	CRANKCASE HEATER
CR	CRANKCASE HEATER

F1S 95 96 4 14 11
 4 97 98 4 12

MADE IN EUROPE

37-0226-1
 3700006